

Proof of service 2

Yes / No. The following work was carried out:	Yes / No. Additional work - Change of:
☒ Oil change service	☐ AdBlue®
☒ Inspection	☐ Brake fluid
☒ With oil change	☐ Diesel fuel filter
☐ With extended scope of inspection	☐ DSG® gear oil
☒ LongLife engine oil used	☐ Haldex coupling: oil
☐ Body check	☐ Air filter insert
☐ Gas system inspection	☐ Filter for liquid gas system
☐ Repairs recommended	☐ Dust and pollen filter insert
☐ Customer request (this should also be noted on the order)	☐ Toothed belt
Service carried out on: 15.07.2020	☐ Spark plugs
at km/miles: 50156	☐
Invoice number: 111	☐
Service carried out by: Stourbridge Service Centre 220 Stourbridge Road Lye West Midlands DY9 7BE TEL: 01384 893527	LongLife mobility guarantee:
Volkswagen Commercial Vehicle dealership stamp	Volkswagen Commercial Vehicle dealership stamp

Your next services	
Service event	Additional work
☐ as per Service interval display	on (Date):
or	or
on (Date):	at (km/miles):
or	at (km/miles):

Documentation of the body check




Fig. 4 Illustration valid for all vehicles and body designs.

Your qualified workshop will indicate damage in → Fig. 4 using the following symbols:

✕ Scratches ○ Dents □ Damaged paintwork △ Stone chipping

Any damage?	Yes: ☐ No: ☐
Description of damage:	
Volkswagen Commercial Vehicle dealership stamp	